## Oil Field Environmental Incident Summary

**Responsible Party:** Zenergy, Inc. **Well Operator:** ZENERGY, INC

Well Name: LINK 10-3H

Field Name: FOREMAN BUTTE Well File #: 24189

Date Incident: 7/10/2013 Time Incident: 13:30 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 102 Sec: 10 Qtr: SE SW

**Location Description:** 

Submitted By: Chad Hillesland Received By:

Contact Person: Chad Hillesland

6100 S YALE AVE STE 1700

TULSA, OK 74136

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spillea	Units	Recoverea	Units	
Oil	3	barrels	1	barrels	
Brine	0	barrels	0	barrels	
Other	0	barrels	0	barrels	

**Description of Other Released Contaminant:** 

On the state of the tree

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Followup Units

## Potential Environmental Impacts:

None.

## Action Taken or Planned:

Sucked up free oil and returned to the tank, steamed off outside of tank, removed stained clay, and informed crew to watch more closely.

Wastes Disposal Location: Indian Hills

Agencies Involved:

## **Updates**

Date: 7/19/2013 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to report spill remained within dike. Oil and Gas lead.